

# CONSUMER CONFIDENCE REPORT 2010

## FOR SAN JOAQUIN COUNTY WATER SYSTEMS

**Water System Name:** Shaded Terrace Water System

**Report Date:** 07/11

**Type of Water Source(s) in Use:** Groundwater wells

**Name of Source(s) in Use:** Well #1

**Drinking Water Source Assessment Information:** A source water assessment for the well of the Shaded Terrace PWS water system was completed in July 2002.

The source is considered most vulnerable to the following activities associated with contaminants detected in the water supply: There have been no contaminants detected in the water supply, however the source is still considered vulnerable to activities located near the drinking water source. The source is considered most vulnerable to the following activities not associated with any detected contaminants: Housing (High density), Transportation corridors (railroads), Wells (water supply).

**Table #1: Sampling Results Showing Detection of Coliform Bacteria**

MICROBIOLOGICAL CONTAMINANTS	HIGHEST NO. of DETECTIONS	NO. of MOS. in VIOLATION	MCL	MCLG	TYPICAL SOURCE OF BACTERIA
Tot. Coliform Bacteria	0 (highest in month)	0	> 1	0	Naturally present in environment
Fecal Coliform and <i>E. coli</i>	0 (year total)	0	> 1	0	Human and animal fecal waste

**Table #2: Sampling Results Showing Detection of Lead and Copper**

LEAD and COPPER	NO. of SAMPLES	90 <sup>TH</sup> Percentile LEVEL	NO. SITES > AL	AL	MCLG	TYPICAL SOURCE OF CONTAMINANT
Lead (ppb)	5	0.8	0	15	2	Internal corrosion of household water plumbing systems; discharge from industrial manufacturers; erosion of natural deposits
Copper (ppb)	5	32	0	1300	170	Internal corrosion of household water plumbing systems; erosion of natural deposits; leaching from wood preservatives

**Table #3: Sampling Results Showing Detection of Sodium and Hardness**

CHEMICAL OR CONSTITUENT	SAMPLE DATE	LEVEL DETECTED	RANGE OF DETECTIONS	MCL	PHG (MCLG)	TYPICAL SOURCE OF CONTAMINANT
Sodium (ppm)	2010	11	–	none	none	Generally found in ground and surface water
Hardness (ppm)	2010	81.1	–	none	none	Generally found in ground and surface water

**Table #4: Detection of Contaminants with a PRIMARY Drinking Water Standard**

CHEMICAL OR CONSTITUENT	SAMPLE DATE	LEVEL DETECTED	RANGE OF DETECTIONS	MCL	PHG (MCLG)	TYPICAL SOURCE OF CONTAMINANT
Gross Alpha Activity (pCi/L)	2003	1.14	–	15	N/A	Erosion of natural deposits
Radium 228 (pCi/L)	2006	0.115	0.00–0.23	5	N/A	Erosion of natural deposits
Aluminum (ppm)	2010	0.46	–	1.00	0.6	Erosion of natural deposits; residue from surface water treatment process
Arsenic (ppb)	2010	3	–	10	N/A	Erosion of natural deposits; run-off from orchards; glass and electronics production wastes
Barium (ppb)	2010	54.8	–	1000	2	Oil drilling and metal refinery waste discharge; erosion of natural deposits
Chromium (ppb)	2010	5	–	50	2.5	Discharge from steel & pulp mills & chrome plating; erosion of natural deposits
Lead (ppb)	2010	0.6	–	50	2	Internal corrosion of household water plumbing systems; discharges from industrial manufacturers; erosion of natural deposits
Nitrate (ppm)	2010	2.2	–	45	45	Run-off and leaching from fertilizer use; leaching from septic tanks; sewage; erosion of natural deposits

# Water System Name: Shaded Terrace Water System

Report Date: 07/11

Type of Water Source(s) in Use: Groundwater wells

Name of Source(s) in Use: Well #1

**Drinking Water Source Assessment Information:** A source water assessment for the well of the Shaded Terrace PWS water system was completed in July 2002. The source is considered most vulnerable to the following activities associated with contaminants detected in the water supply: There have been no contaminants detected in the water supply, however the source is still considered vulnerable to activities located near the drinking water source. The source is considered most vulnerable to the following activities not associated with any detected contaminants: Housing (High density), Transportation corridors (railroads), Wells ( water supply).

**Table #1: Sampling Results Showing Detection of Coliform Bacteria**

MICROBIOLOGICAL CONTAMINANTS	HIGHEST NO. of DETECTIONS	NO. of MOS. in VIOLATION	MCL	MCLG	TYPICAL SOURCE OF BACTERIA
Tot. Coliform Bacteria	0 (highest in month)	0	> 1	0	Naturally present in environment
Fecal Coliform and <i>E. coli</i>	0 (year total)	0	> 1	0	Human and animal fecal waste

**Table #2: Sampling Results Showing Detection of Lead and Copper**

LEAD and COPPER	NO. of SAMPLES	90 <sup>TH</sup> Percentile LEVEL	NO. SITES > AL AL		MCLG	TYPICAL SOURCE OF CONTAMINANT
Lead (ppb)	5	0.8	0	15	2	Internal corrosion of household water plumbing systems; discharge from industrial manufacturers; erosion of natural deposits
Copper (ppb)	5	32	0	1300	170	Internal corrosion of household water plumbing systems; erosion of natural deposits; leaching from wood preservatives

**Table #3: Sampling Results Showing Detection of Sodium and Hardness**

CHEMICAL OR CONSTITUENT	SAMPLE DATE	LEVEL DETECTED	RANGE OF DETECTIONS	MCL	PHG (MCLG)	TYPICAL SOURCE OF CONTAMINANT
Sodium (ppm)	2010	11	–	none	none	Generally found in ground and surface water
Hardness (ppm)	2010	81.1	–	none	none	Generally found in ground and surface water

**Table #4: Detection of Contaminants with a PRIMARY Drinking Water Standard**

CHEMICAL OR CONSTITUENT	SAMPLE DATE	LEVEL DETECTED	RANGE OF DETECTIONS	MCL	PHG (MCLG)	TYPICAL SOURCE OF CONTAMINANT
Gross Alpha Activity (pCi/L)	2003	1.14	–	15	N/A	Erosion of natural deposits
Radium 228 (pCi/L)	2006	0.115	0.00–0.23	5	N/A	Erosion of natural deposits
Aluminum (ppm)	2010	0.46	–	1.00	0.6	Erosion of natural deposits; residue from surface water treatment process
Arsenic (ppb)	2010	3	–	10	N/A	Erosion of natural deposits; run-off from orchards; glass and electronics production wastes
Barium (ppb)	2010	54.8	–	1000	2	Oil drilling and metal refinery waste discharge; erosion of natural deposits
Chromium (ppb)	2010	5	–	50	2.5	Discharge from steel & pulp mills & chrome plating; erosion of natural deposits
Lead (ppb)	2010	0.6	–	50	2	Internal corrosion of household water plumbing systems; discharges from industrial manufacturers; erosion of natural deposits
Nitrate (ppm)	2010	2.2	–	45	45	Run-off and leaching from fertilizer use; leaching from septic tanks; sewage; erosion of natural deposits