


CORNER RECORD

Document Number CR-92-009

City of _____ County of San Joaquin, California

Brief Legal Description PARCEL B, PM 10-84



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 12-13-91

**COORDINATES
(Optional)**

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner - Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: FD 3/4" IRON PINS (REBAR) AROUND PARCEL B ACCORDING TO PM 10-84

A description of the physical condition of the monument as found and as set or reset: Set witness monuments in the event the iron pins are disturbed during construction on state Highway Route 120

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on 2-21 19 92.

Signed [Signature] L.S. or R.C.E. Number 4466
License Expiration Date 9-30-93



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received February 25, 19 92 and examined and filed March 2, 19 92.

Signed [Signature] Title Chief Deputy County Surveyor

County Surveyor's Comment _____

