


CORNER RECORD

City of Stockton

Document Number CR-97-06
County of San Joaquin, California

Brief Legal Description SE 1/4 OF SE 1/4 OF SECTION 11 OF THE C.M. WEBER GRANT, Lot 305 of Mosswood Park
Map 'C' Maps and Plats, Book 11 Page 4.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 11/96

COORDINATES

(Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner : Found reference ties as shown on corner record(see sketch). Reset Northeast property corner of Lot 305 as shown on Maps and Plats Book 11, Page 4, destroyed during construction of sanitary sewer line using reference tie outs(see sketch).

A description of the physical condition of the monument as found and as set or reset: Found concrete nails and shiners in pavement and chiseled crows foot on concrete abutment(see sketch). Reset property corner is 3/4" iron pin with plastic cap stamped "City of Stockton".


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on December 31, 19 96.
Signed Robert E Chesner L.S. or R.C.E. Number 6670
Title SURVEYING SUPERVISOR, City of Stockton Public Works Department



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received February 27, 19 97 and examined and filed March 25, 19 97.
Signed Manuel Lopez Title County Surveyor



County Surveyor's Comment _____

(D.D. SHEET NO. 34)

MADRID PARK
MOSSWOOD 11-4
MXP

LOT 305

WAT AVE

END SHOWN
NAD C.R. - 97-05
3/8 20

SET 3ft
I.P.M. WITH
PULSIC S. 1000
WEST 1/2

END
CROSS FOOT
ON CONC. ABUT.
PER C.R. - 97-05

S. EL DORADO ST.

END SHOWN
NAD C.R. - 97-05

