


CORNER RECORD

City of Stockton

Document Number 00-151
County of San Joaquin, California

Brief Legal Description A portion of Block 10 East of Center Street, as shown on Record of Survey, Book 34, page 40, San Joaquin County Records, City of Stockton N.



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other

Date of Survey Dec. 5, 1999

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found monuments as noted on sketch on reverse side

A description of the physical condition of the monument as found and as set or reset: Record of Survey Book 34, Page 40, San Joaquin County Records, shows that a chiseled "t" witness corner was set for the southwest corner of the property described in Instrument N° 84042003 San Joaquin County Records, and a "spike" witness corner was set for the southeast corner of said property. These witness corners are in jeopardy of being destroyed. New witness corners were set as shown on sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Feb. 16, 2000.

Signed Michael L. Quaratoro or R.C.E. Number 4450



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Feb. 17, 2000 and examined and filed February 23, 2000.

Signed Henry M. Hirata R.C.E. No. 21258
Title _____ County Surveyor



County Surveyors Comment _____

Reference

(A) Indicates Record of Survey, Book 34, page 40, S.J.C.R.

Legend

- (M) Indicates measured
- S.J.C.R. Indicates San Joaquin County Records
- Indicates Set Lead and Brass Nail with tag L.S. 4450 in concrete curb
- Indicates Found monument as noted

Scale: 1" = 30'

