CORNER RECORD	Docunt Number <u>CR-01-118</u>
City of	County of San Joaquin, California
Brief Legal Description A portion of the easterly property line of that 0.840 a	cre parcel of land as shown on Record of
Survey, Volume 8, at page 167, San Joaquin County Records	
CORNER TYPE	COORDINATES (Optional)
Government Corner Control Property X Rancho Other	ZoneNAD27NAD83 NAD83 Epoch Elev
Date of Survey October 23, 2001	Vert. Datum: NGVD29 NAVD88 Meas. Units: Metric Imperial
Corner - Left as found Found and tagged Established	Reestablished X Rebuilt
Identification and type of corner found: Evidence used to identify or procedure Found 1" iron pipes as shown on R.S. 8-167 along the northerly right-of-way on line of 0.840 acre parcel up to Five Mile Slough at record bearings and distance 1" pipes as the basis of bearings. Tied into a found 1" iron pipe, also set on R.S. access road as shown on Page 2 of this corner record.	f Lincoln Road. Set corners along the easterly es as shown on R.S. 8-167 using the aforesaid
A description of the physical condition of the monument as found and as set or reset: Set 3 /4 " by 30" long iron rebar pins with a plastic cap stamped "L.S. 7520" at the three corners shown on Page 2 of this corner record.	
SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance the Land Surveyors' Act on October 23, 2001. Signed Lard W. Janphea L.S. 7520	EXPIRES 12/31/03 NO. 7520 NO. 7520
COUNTY SURVEYOR'S STATEMENT This Corner Record was received October 24,2001 and exame and filed October 27,2001. Signed Momen M. January R.C.E. No. 26 Title Interim County Surveyor	3/\
County Surveyor's Comment	OF CALIFORNIA
(D.D. Sheet No. <u>29</u>)	

