


# CORNER RECORD

City of \_\_\_\_\_ Document Number 04-09  
County of San Joaquin, California

Brief Legal Description Northerly Angle point in Easterly line, Parcel 1, per Record of Survey Book 21, Page 140, San Joaquin County Records.



### CORNER TYPE

- Government Corner  Control   
Meander  Property   
Rancho  Other

Date of Survey July 17, 2003

### COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
The position of the valve stem was re-established using the ties shown on CR-03-06, S.J.C.R.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_  
—●— Indicates Found Monument as noted.  
—○— Indicates set brass tag stamped L.S. 4450 with rivet on steel irrigation valve.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on July 28, 2003.

Signed Michael L. Quarteroli L.S. Number 4450



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 6, 2003 and examined and filed JUNE 25, 2004.

Signed Jeff Lund L.S. Number 4440

Title Asst. County Surveyor

County Surveyor's Comment \_\_\_\_\_



# LEGEND

- FD. INDICATES FOUND ON THIS SURVEY
- S.F.N. INDICATES SEARCHED, FOUND NOTHING
- R.S. INDICATES RECORD OF SURVEY, BOOK AND PAGE, S.J.C.R.
- S.J.C.R. INDICATES SAN JOAQUIN COUNTY RECORDS
- (M) INDICATES MEASURED

# BASIS OF BEARINGS

THE BEARING BETWEEN THE SW CORNER OF SECTION 12, T.2S., R.9E., M.D.B.& M. AND THE FOUND PK NAIL NEAR THE CENTERLINE INTERSECTION OF RIVER ROAD AND SUTLIFF AVE. BEARS N 88° 43' 45" W PER CR-03-06, S.J.C.R.

