


# CORNER RECORD

Document Number 07-09  
County of SAN JOAQUIN, California

City of \_\_\_\_\_

Brief Legal Description SITUATED IN THE NORTHWEST QUARTER OF SECTION 66 OF THE  
C.M. WEBER GRANT.



## CORNER TYPE

Government Corner ☐ Control ☐  
Meander ☐ Property ☐  
Rancho ☐ Other ☒

## COORDINATES (Optional)

N \_\_\_\_\_  
E \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27 ☐ NAD83 ☐  
NAD83 Epoch \_\_\_\_\_  
Elevation \_\_\_\_\_  
Vert. Datum: NVGD29 ☐ NVGD88 ☐  
Meas Units: Metric ☐ Imperial ☐

Date of Survey MAY 3, 2006

Corner— Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.  
FOUND 3/4" REBAR TAGGED RCE 15831 IN MONUMENT WELL PER DESCRIPTION SHOWN IN  
SURVEY FIELD BOOK No. 690 PAGE 63, ON FILE WITH SAN JOAQUIN COUNTY  
SURVEYOR'S OFFICE, AND IDENTIFIED AS STATION 6+46.

A description of the physical condition of the monument as found and as set or reset:  
FOUND 3/4" REBAR TAGGED RCE 15831 IN MONUMENT WELL PER DESCRIPTION FOUND IN  
SAN JOAQUIN COUNTY SURVEY FIELD BOOK No. 690 PAGE 63, IDENTIFIED AS STATION 6+46.  
SET WITNESS TIES AS SHOWN ON DIAGRAM ON PAGE 2 OF 2 HEREON.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
the Land Surveyor's Act on 2-12, 2007.

Signed \_\_\_\_\_ P.L.S. or R.C.E. Number LS 6805

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 2-15, 2007 and examined  
and filed 3-29, 2007.

Signed [Signature] P.L.S. or R.C.E. Number 4440

Title Assistant County Surveyor

County Surveyor's Comment \_\_\_\_\_



