


CORNER RECORD

Document Number 07-10

City of _____

County of SAN JOAQUIN, California

Brief Legal Description SITUATED IN THE NORTHWEST QUARTER OF SECTION 66 OF THE
C.M. WEBER GRANT.



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☐
Rancho ☐ Other ☒

COORDINATES (Optional)

N _____
E _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elevation _____
Vert. Datum: NVGD29 ☐ NVGD88 ☐
Meas Units: Metric ☐ Imperial ☐

Date of Survey AUGUST 26, 2006

Corner— Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.

3/4" REBAR TAGGED RCE 15831 IN MONUMENT WELL PER DESCRIPTION FOUND IN
SAN JOAQUIN COUNTY SURVEY FIELD BOOK No. 690 PAGE 63, IDENTIFIED AS STATION 6+46.
WAS DESTROYED BY CONSTRUCTION. REESTABLISHED CORNER LOCATION PER TIES
ON PAGE 2 OF 2 HEREON.

A description of the physical condition of the monument as found and as set or reset:

SET 3/4" X 24" IRON PIPE TAGGED LS 6805, IN MONUMENT WELL.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 2-12, 2007.

Signed _____ P.L.S. or R.C.E. Number LS 6805

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 2-15, 2007 and examined
and filed 3-29, 2007.

Signed _____ P.L.S. or R.C.E. Number 4440

Title Assistant County Surveyor

County Surveyor's Comment _____

