


CORNER RECORD

Document Number 07-11
County of SAN JOAQUIN, California

City of _____

Brief Legal Description SITUATED IN THE SOUTHWEST QUARTER OF SECTION 65 OF THE
C.M. WEBER GRANT.



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☐
Rancho ☐ Other ☒

Date of Survey MAY 3, 2006

COORDINATES (Optional)

N _____
E _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elevation _____
Vert. Datum: NVGD29 ☐ NVGD88 ☐
Meas Units: Metric ☐ Imperial ☐

Corner— Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.
FOUND NAIL AND SHINER IN JOINT POLES PER DESCRIPTION SHOWN IN SAN JOAQUIN
COUNTY SURVEYOR'S FIELD BOOK No. 695, PAGE 16 ON FILE WITH SAN JOAQUIN COUNTY
SURVEYOR'S OFFICE, IDENTIFIED AS STATION 31+23.11.

A description of the physical condition of the monument as found and as set or reset:
FOUND NAIL AND SHINER IN JOINT POLES PER DESCRIPTION SHOWN IN SAN JOAQUIN
COUNTY SURVEYOR'S FIELD BOOK No. 695, PAGE 16, IDENTIFIED AS STATION 31+23.11.
SET WITNESS TIES AS SHOWN ON DIAGRAM ON PAGE 2 OF 2 HEREON.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 2-12, 2007.

Signed _____ P.L.S. or R.C.E. Number LS 6805

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 2-15, 2007 and examined
and filed 3-29, 2007.

Signed Jeff D. Lund P.L.S. or R.C.E. Number 4440

Title Assistant County Surveyor

County Surveyor's Comment _____

