


CORNER RECORD

Document Number 07-12
City of _____ County of SAN JOAQUIN, California

Brief Legal Description SITUATED IN THE SOUTHWEST QUARTER OF SECTION 65 OF THE
C.M. WEBER GRANT.



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☐
Rancho ☐ Other ☒

COORDINATES (Optional)

N _____
E _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elevation _____
Vert. Datum: NVGD29 ☐ NVGD88 ☐
Meas Units: Metric ☐ Imperial ☐

Date of Survey AUGUST 26, 2006

Corner— Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.

REESTABLISHED CORNER LOCATION PER DESCRIPTION FOUND IN SAN JOAQUIN COUNTY

SURVEYOR'S FIELD BOOK No. 695 PAGE 16, IDENTIFIED AS STATION 31+23.11 PER TIES ON
PAGE 2 OF 2 HEREON.

A description of the physical condition of the monument as found and as set or reset: _____

SET 3/4" X 24" IRON PIPE, TAGGED LS 6805, IN MONUMENT WELL.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 2-12, 2007.

Signed _____ P.L.S. or R.C.E. Number LS 6805

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 2-15, 2007 and examined
and filed 3-29, 2007.

Signed Jeff Lund P.L.S. or R.C.E. Number 4440

Title Assistant County Surveyor

County Surveyor's Comment _____

