
## CORNER RECORD Document Number <u>CR-58-17</u> City of \_\_\_\_\_ County of San Joaquin, California Brief Legal Description EAST MAIN STREET @ WALKER LANE (14' NORTH OF INTERSECTION) **CORNER TYPE** COORDINATES (Optional) Government Corner Control NAD27 ☐ NAD83 ☐ Zone Meander Property NAD83 Epoch\_ Rancho Other Elev. Vert. Datúm: NGVD29 □ NAVD88 Date of Survey June 29, 2005 Meas. Units: Metric Imperial 🖾 Corner -Left as found ☑ Found and tagged ☐ Established ☐ Reestablished Rebuilt 🔲 Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner; SEE SKETCH ON BACKSIDE. A description of the physical condition of the monument as found and as set or reset: SEE SKETCH ON BACKSIDE. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on <u>Jan. 14</u>, 2008. Signed Manuel R.C.E. Number <u>C30890</u> COUNTY SURVEYOR'S STATEMENT This Corner Record was received **JANUARY 17**, 2008 and examined JANUARY 18 and filed \_\_\_\_ Signed \_\_\_\_\_ P.L.S. No. 4440 Title Assistant County Surveyor County Surveyor's Comment\_ No. 4440 THIS CORNER RECORD IS NOT IN COMPLIANCE WITH BOARD RULE 464(c)

**Expires** 

(D.D. Sheet No. 32 ( )

REGARDING SUBMITTAL WITHIN 90 DAYS FROM THE DATE OF SURVEY.



Note: Found Monuments are not tagged unless otherwise noted.

"No Attempt Was Made to Verify the Monument(s)"

FP=Fence Post
GP=Guy Post
JP=Joint Pole
PP=Power Pole
SP=Service Pole
TP=Telephone Pole
S.F.N=Searched Found Nothing
N.T.S.=Not To Scale
Set=Conc. Nail with Brass Washer Stamped
"S.J. Co.", unless otherwise noted

Note: Set Ties are Brass Washers Stamped "S.J.Co. PUBLIC WORKS"