
CORNER RECORD			Document Number CR-09-23		
City of			County of		Californic
Brief Leaal Description	WEST RIPON ROAD @ MANTECA	ROAD			
	SOUTHWEST CORNER OF SECTION				and the second second second
	CORNER TYPE		CO(ORDINATES (Opt	ional)
21		control □ roperty □ other □	NAD83 Epoc	NAD27 h	□ NAD83 □
T2S R7E	Rancho LI O Date of Survey January 7, 2	20		NGVD29 □	NAVD88 ☐ Imperial ☒
Corner - Left as f	ound Found and tagged	Established	☐ Reestablish	ned 🔲 Rebu	vilt 🗆
Identification and typ	oe of corner found: Evidence used (SIDE.				
GLE GREICH ON DACE	OIDL.				
2					
The state of the s	OIDE.				
	SURVEYOR'S STATEMENT	29		SIONAL I	AND
	vas prepared by me or under my di 'Act on <u>February</u> 17 ¹ 4		ormance with	OH LICE	NSE OF
Signed 76	P.L.S. Nu		<u>)</u>		8470
	COUNTY SURVEYOR'S STATEMEN			S. E.D. 12	0110
	was received February 19	7 _, 2009 and	examined	TATE OF	CALIFORNIE
and filed MAR	H 11 , 2009.	9	₩.	Or Or	CAL
Signed Mo	ran M. Have	_ R.C.E. No	23341	OROFES	SION
Title County Surv	reyor	N		PROFES AND PROFES	M. GAL FE
County Surveyor's	Comment			REGI	廟
8				No. 26 ★ EXP. 3-31	
(D.D. Sheet Nos. 58 Job No. 220790	3 & 64 & 65)		× +	STATE OF C	ALIFORNIA







Note: Found Monuments are not tagged nor of Record; Unless otherwise noted.

"No Attempt Was Made to Verify the Monument(s)"

No Attempt

NTS= Not to Scale

FR=Fence Post

GR=Guy Post

JR=Joint Pole

PP=Power Pole

SP=Service Pole

JR=Telephone Pole

S.F.N=Searched Found Nothing

N.J.S.=Not To Scale

Set=Gonc. Nail: with Brass Washer Stamped

S.J. Co., unless otherwise noted