

# CORNER RECORD

Document Number CR 12-105  
County of SAN JOAQUIN, California

City of RIPON

Brief Legal Description MONUMENT APPROXIMATELY 1162'± EAST ALONG THE SECTION LINE FROM THE APPARENT SOUTHWEST CORNER OF SECTION 25, T.2S., R.7E., M.D.B.&M.

## CORNER TYPE

## COORDINATES (Optional)

NW 1/4	NE 1/4
SW 1/4	SE 1/4

Government Corner ☐ Control ☐  
Meander ☐ Property ☐  
Rancho ☐ Other ☒

N \_\_\_\_\_  
E \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27 ☐ NAD83 ☐  
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NVGD29 ☐ NVGD88 ☐  
Meas. Units: Metric ☐ Imperial ☐

SEC.25 T2S, R7E

Date of Survey 2-16-2012

Corner— Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
1-1/2" IRON PIPE NOT TAGGED, APPROXIMATELY 1162'± EAST ALONG THE SECTION LINE FROM THE APPARENT SW CORNER OF SECTION 25, T.2S., R.7E., M.D.B.&M. WAS DESTROYED DURING CONSTRUCTION. FOUND WITNESS CORNERS AS SHOWN ON CORNER RECORD DOCUMENT NUMBER 11-192.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_  
SET 3/4" x 24" IRON PIPE WITH PLASTIC CAP STAMPED L.S. 6953 FROM TIES AS SHOWN ON PAGE 2.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on FEBRUARY 20,, 2012,

Signed [Signature] P.L.S. or R.C.E. Number 6953



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MARCH 15, 2012 and examined and filed MARCH 19, 2012.

Signed Thomas M. Gau P.L.S. or R.C.E. No: 26994

Title COUNTY SURVEYOR

County Surveyor's Comment \_\_\_\_\_



