
## Document Number CR-13-187 CORNER RECORD City of \_\_\_\_\_ County of San Joaquin, Brief Legal Description \_\_\_\_MACARTHUR DRIVE 127' +/- AND 268' +/- NORTH OF LINNE ROAD (ON SECTION 3 WEST LINE, TOWNSHIP 3 SOUTH, RANGE 5 EAST, MOUNT DIABLO BASE AND MERIDIAN) CORNER TYPE COORDINATES (Optional) Government Corner Control Zone\_ NAD27 ☐ NAD83 ☐ Meander Property NAD83 Epoch Other Rancho Elev. Vert. Datum: NGVD29 NAVD88 Date of Survey \_\_\_\_ May 02, 2013 Meas. Units: Metric Imperial 🖾 Left as found Found and tagged □ Established Reestablished Corner -Rebuilt Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: SEE SKETCH ON BACKSIDE. A description of the physical condition of the monument as found and as set or reset: SEE SKETCH ON BACKSIDE. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_\_ June 3 \_\_\_\_\_, 2013. P.L.S. Number 8657 LICENSE COUNTY SURVEYOR'S STATEMENT This Corner Record was received June 3, 2013 and examined and filed June 18 \_, 2013. Title County Surveyor County Surveyor's Comment\_\_\_\_\_

(D.D. Sheet Nos. 68 & 69) (Job No. 220080)



Note: Found Monuments are not tagged unless otherwise noted.

"No Attempt Was Made to Verify the Monument(s)"

Set=Conc. Nail with Brass Washer Stamped
"S.J. Co.", unless otherwise noted
Fd.=Found Conc. Nail with Brass Washer Stamped
"S.J. Co.", unless otherwise noted
CR=Corner Record
FP=Fence Post
JP=Joint Pole
LP=Light Pole
PP=Power Pole
GP=Guy Pole
SP=Service Pole
TP=Telephone Pole
S.F.N.=Sernched Found Nothing
N.T.S.=Not To Scale
M&P=Maps & Plats
PM=Parcel Map
RS=Record of Survey

FB=Field Book