


CORNER RECORD

Document Number CR-13-189
City of RIPON County of SAN JOAQUIN, California

Brief Legal Description LOT 4, 36 MEP 37



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey 5/15/13

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NAVD88 ☐
Meas. Units: Metric ☐ Imperial ☒

Corner - Left as found ☒ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE SKETCH ON BACK

A description of the physical condition of the monument as found and as set or reset:

FOUND SEVERAL MONUMENTS IN GOOD SHAPE
AS PER 36 MEP 37. SET TWO MONUMENTS
UTILIZING RECORD DATA.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on MAY 22 2013

Signed Michael T. Turnor (P.L.S. or R.C.E. No. 7454)



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 4, 2013

and examined and filed June 18, 2013

Signed Thomas M. Gau (P.L.S. or R.C.E. No. 26994)

Title County Surveyor

County Surveyor's Comment _____

