
CORNER RECORD Document Number_CR-14-748 City of County of San Joaquin, Brief Legal Description _____CLOVER ROAD 1980'± WEST OF TRACY BLVD. (In Rancho El Pescadero) CORNER TYPE COORDINATES (Optional) Government Corner Control NAD27 ☐ NAD83 ☐ Meander Property NAD83 Epoch Rancho ☐ Other Elev. Vert. Datum: NGVD29 □ Date of Survey _____August 06, 2014 Meas. Units: Metric ☐ Imperial ☒ Corner -Left as found ☐ Found and tagged ☐ Established ☐ Reestablished Rebuilt | Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: SEE SKETCH ON BACKSIDE. A description of the physical condition of the monument as found and as set or reset:_____ SEE SKETCH ON BACKSIDE. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____October 10 , 2014. LICENSE COUNTY SURVEYOR'S STATEMENT This Corner Record was received <u>October 10</u>, 2014 and examined ____, 2014. MC R.C.E. No. 26994 Title County Surveyor County Surveyor's Comment_____

(D.D. Sheet No. 53B) (Job No. 220102)





Note: Found Monuments are not tagged unless otherwise noted.

"No Attempt Was Made to Verify the Monument(s)"

Set=Conc. Nail with Brass Washer Stamped
"S.J. Co.", unless otherwise noted
Fd.=Found Conc. Nail with Brass Washer Stamped
"S.J. Co.", unless otherwise noted
CR=Corner Record
FP=Fence Post
JP=Joint Pole
LP=Light Pole
LP=Light Pole
PP=Power Pole
GP=Guy Pole
SP=Service Pole
IP=Telephone Pole
S.F.N.=Searched Found Nothing
N.T.S.=Not To Scale
M&P=Maps & Plats
PM=Parcel Map
RS=Record of Survey
FB=Field Book