
CORNER RECORD

City of SARGENT ROAD 1909' ± WEST OF DAVIS ROAD (ON THE SOUTH LINE OF SECTION 5 , TOWNSHIP 3 NORTH, RANGE CORNER TYPE Government Corner	
CORNER TYPE Government Corner Control Meander Property Rancho Other	COORDINATES (Optional) N ENAD27 NAD83 NAD83 Epoch Elev Vert. Datum: NGVD29 NAVD88 N
CORNER TYPE Government Corner Control Meander Property Rancho Other Other	COORDINATES (Optional) N E ZoneNAD27 NAD83 NAD83 Epoch Elev Vert. Datum: NGVD29 NAVD88
Government Corner Control Meander Property Rancho Other	N
Date of Survey June 3, 2015	
Corner - Left as found ☑ Found and tagged ☐ Established	☐ Reestablished ☐ Rebuilt ☐
A description of the physical condition of the monument as found and	
SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformation the Land Surveyors' Act onJuly 13, 2015. Signed	LICENSE No. 8657 d examined 4842
County Surveyor County Surveyor's Comment (D.D. Sheet No. 14) (Job No. 544002)	LICENSE No. 4842





Note: Found Monuments are not tagged unless otherwise noted.

"No Attempt Was Made to Verify the Monument(s)"

Set=Conc. Nail with Brass Washer Stamped
"S.J. Co.", unless otherwise noted
Fd.=Found Conc. Nail with Brass Washer Stamped
"S.J. Co.", unless otherwise noted
CR=Corner Record
FP=Fence Post
JP=Joint Pole
LP=Light Pole
PP=Power Pole
GP=Guy Pole
SP=Service Pole
TP=Telephone Pole
S.F.N.=Searched Found Nothing
N.T.S.=Not To Scale
M&P=Maps & Plats
PM=Parcel Map
RS=Record of Survey
FB=Field Book