


CORNER RECORD

Document Number CR-15-236

City of Stockton

County of San Joaquin, California

Brief Legal Description Being the Southeasterly corner of Lot 92 per M. & P. 20-31, S.J.C.R.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

COORDINATES(Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NADV88
 Meas. Units: Metric Imperial

Sec. 18, T.2N., R.6E.,
 M.D.B. & M.

Date of Survey August 6, 2015

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

See Sheet 2

A description of the physical condition of the monument as found and as set or reset:

See Sheet 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on August 7, 2015.

Signed Michael L. Quatambi P.L.S. or R.C.E. No.: L.S. 4450



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received September 11, 2015 and examined


and filed October 9, 2015.

Signed Warren D. Smith P.L.S. or R.C.E. No.: 4842

Title Acting County Surveyor

County Surveyor's Comment _____





SCALE: 1" = 40'
2015-156

LEGEND

- + INDICATES FOUND CHISELED CROSS PER (A), UNLESS OTHERWISE NOTED
- INDICATES SET 1" DIA. BRASS DISC STAMPED L.S. 4450 WITNESS CORNER
- FD. INDICATES FOUND ON THIS SURVEY
- (M) INDICATES MEASURED ON THIS SURVEY
- M. & P. INDICATES MAPS AND PLATS, BOOK AND PAGE, S.J.C.R.
- S.J.C.R. INDICATES SAN JOAQUIN COUNTY RECORDS

REFERENCE

(A) M. & P. 20-31, S.J.C.R.

NOTE

NO PRE-CONSTRUCTION CORNER RECORD WAS PREPARED PER SEC. 8771. THIS CORNER RECORD IS POST-CONSTRUCTION AND ESTABLISHES THE POSITION OF THE DESTROYED WITNESS CORNER WITH SHOWN MONUMENTS.

