CR-17-272 CORNER RECORD Agency Index Document Number Stockton County of San joaquin Offset of the East end of round corner of Lot 225, 21 M.P. 75 Brief Legal Description **CORNER TYPE** COORDINATES (Optional) Government Corner Control Elevation U.S. Survey Foot Units Meander Property Metric Rancho Other Horizontal Datum Zone Epoch Date Date of Survey August 24, 2017 Vertical Datum Complies with Public Resources Code §§8801-8819 S4 C.M. Webber Grant Complies with Public Resources Code §§8890-8902 PLS Act Ref.: 8765(d) X 8771 Other: Left as found Established Pre-Construction Rebuilt Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: ✓ See sheet #2 for description(s): Before the sidewalk was replaced, a cut cross was found and reference points were set. After the sidewalk was replaced, the reference points were used to set a 1" brass disc stamped "LS 6947" in the location of the destroyed cut cross. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on August 25, 2017 6947 P.L.S. or R.C.E. No. Signed COUNTY SURVEYOR'S STATEMENT This Corner Record was received August 31, 2017

September 8, 2017.

P.L.S. or R.C.E. No. 4842

and examined and filed

County Surveyor's Comment

County Surveyor

Signed

Title

