


CORNER RECORD

Agency Index CR-18-21
Document Number _____

City of STOCKTON County of SAN JOAQUIN, California
Brief Legal Description 5' WEST AND 3' SOUTH OF BLOCK CORNER AS SHOWN ON 32-R.S.-90

CORNER TYPE

COORDINATES (Optional)



BLK. 77 SEC. 20
C.M.W. GRANT

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey August 31, 2017

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

- PLS Act Ref.: 8765(d) 8771 8773 Other:
- Corner/
Monument: Left as found Established Rebuilt Pre-Construction
- Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

FOUND CHISELED CROSS IN SIDEWALK AS SHOWN ON 32-R.S.-90. LEFT AS FOUND. SEE SKETCH ON BACK

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on October 6, 2017

Signed [Signature] P.L.S. or R.C.E. No. 8971



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received December 14, 2017

and examined and filed January 18, 2018

Signed Warren D. Smith P.L.S. or R.C.E. No. 4842

Title County Surveyor

County Surveyor's Comment





STREET

GRANT

SIDEWALK

210 N GRANT ST
139-300-13

FOUND CHISELED
CROSS IN SIDEWALK
PER R.S. 32-80

SIDEWALK

PK NAIL &
SHINER

12.89'

PK NAIL &
SHINER IN
TP

7.11'

16.88'

PK NAIL &
SHINER

12.34'

PK NAIL &
SHINER

CHANNEL

STREET