CR-18-25 **CORNER RECORD** Agency Index **Document Number** County of City of STOCKTON SAN JOAQUIN , California 5' NORTH AND 5' EAST OF BLOCK CORNER AS SHOWN ON 32-R.S.-90 Brief Legal Description **COORDINATES (Optional) CORNER TYPE** N. Government Corner Control Elevation U.S. Survey Foot Property Meander Units Metric Rancho Other Horizontal Datum Zone Epoch Date Date of Survey August 31, 2017 Vertical Datum BLK. 77 SEC. 20 Complies with Public Resources Code §§8801-8819 C.M.W. GRANT Complies with Public Resources Code §§8890-8902 PLS Act Ref.: 8765(d) X 8771 8773 Other: Left as found Established Rebuilt Pre-Construction Cornerl Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: √ See sheet #2 for description(s): FOUND CHISELED CROSS IN SIDEWALK AS SHOWN ON 32-R.S.-90. LEFT AS FOUND. SEE SKETCH ON BACK SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with POYTHREAS the Professional Land Surveyors' Act on October 6, 2017 Signed P.L.S. or-R.C.E. No. COUNTY SURVEYOR'S STATEMENT

This Corner Record was received December

December 14, 2017

and examined and filed January 18, 2018

Signed Nan D. J. P.L.S. or R.C.E. No. 4842

Title County Surveyor

County Surveyor's Comment



