CORNER RECORD

Agency Index ____CR-18-47 Document Number San Joaquin County of City of Brief Legal Description Corner common to Sections 15, 16, 21 & 22 T.1N., R.9E., M.D.M. COORDINATES (Optional) CORNER TYPE E. 6422697.89 N. 2161518.55 Control Elevation Government Corner 16 15 X U.S. Survey Foot Metric Property Units Meander CCS83 Other Rancho Horizontal Datum Zone 3 Epoch Date 2010 Vertical Datum Date of Survey January 4, 2018 ✓ Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8773 X 8771 8765(d) PLS Act Ref .: Pre-Construction Rebuilt Established Left as found Corner/ Post-Construction Referenced Monument: Reestablished Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: ✓ See sheet #2 for description(s): Found 2 1/2" Brass Disk in concrete, "California Department of Transportation" in monument well per R.S. 35-29 M.&P., S.J.C.R.. No attempt was made to determine validity of monument or its proper location in relation to the legal boundary lines in the area. Coordinates provided per static survey and conventional ties. See "Sheet 2". AURENS M. SURVEYOR'S STATEMENT GILMORE NO. L 8339 This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on January 16, 2018 P.L.S. or R.C.E. No. Signed COUNTY SURVEYOR'S STATEMENT January 18, 2018 This Corner Record was received February 7, 2018. and examined and filed P.L.S. or R.C.E. No. 4842 No 4842 Signed County Surveyor Title **County Surveyor's Comment**

