

CORNER RECORD

Agency Index CR-18-87


Document Number _____

City of Near Town of Banta County of San Joaquin County, California

Brief Legal Description LOT 7, TRACT NO. 1271 (23 M&P 52)

CORNER TYPE

COORDINATES (Optional)



- Government Corner
- Meander
- Rancho
- Control
- Property
- Other

Date of Survey March 16, 2018

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum NAD83

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref.: 8765(d) 8771 8773 Other:

Corner/Monument: Left as found Established Rebuilt Pre-Construction

Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

Set rebar and cap, LS 8164, at corners, or as witness to the corners, of Lot 7, Tract No. 1271 (23 M&P 52), See attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on March 24, 2018

Signed *S. Kyle Tractor* P.L.S. or R.C.E. No. LS 8164



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received March 26, 2018

and examined and filed March 29, 2018

Signed *Warren D. Smith* P.L.S. or R.C.E. No. 4842

Title County Surveyor

County Surveyor's Comment



GRANT LINE ROAD

LEGEND

- FOUND REBAR AND CAP, RCE 14269, IN WELL PER (1)
- SET REBAR AND CAP, LS 8164
- ⊙ SET WITNESS CORNER REBAR AND CAP "WC LS 8164"
- - - TIE LINE
- x - FENCE LINE
- PL PROPERTY LINE
- (1) REFERS TO TRACT NO. 1271 (23 M&P 52)

