


# CORNER RECORD

Agency Index CR-18-96  
Document Number \_\_\_\_\_

City of \_\_\_\_\_ County of San Joaquin, California  
Brief Legal Description block corner in Sec 34 T.1 S., R.8 E. M.D.M.

### CORNER TYPE

### COORDINATES (Optional)



- Government Corner     Control  
 Meander                     Property  
 Rancho                          Other

N. \_\_\_\_\_ E. \_\_\_\_\_

Elevation \_\_\_\_\_

Units     Metric                     U.S. Survey Foot

Horizontal Datum \_\_\_\_\_

Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_

Vertical Datum \_\_\_\_\_

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref.:     8765(d)                     8771                     8773                     Other:

Corner/  
Monument:     Left as found                     Established                     Rebuilt                     Pre-Construction  
                   Found and tagged                     Reestablished                     Referenced                     Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

Found 3/4" iron pipe (shown on RS 36-143 as former property corner) in monument well with no lid, down 1.3 ft, set cotton spindle with brass Caltrans washer at surface.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
the Professional Land Surveyors' Act on April 15, 2018

Signed [Signature] P.L.S. or R.C.E. No. 6406



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received May 8, 2018  
and examined and filed May 8, 2018

Signed James E. Hart P.L.S. or R.C.E. No. 8657

Title Acting County Surveyor

County Surveyor's Comment



D.D. Sheet No. 61

