

# CORNER RECORD


Agency Index CR-18-121  
Document Number \_\_\_\_\_

City of TRACY County of SAN JOAQUIN, California

Brief Legal Description CORRAL HOLLOW ROAD

### CORNER TYPE

### COORDINATES (Optional)



Government Corner  Control   
Meander  Property   
Rancho  Other

N. \_\_\_\_\_ E. \_\_\_\_\_

Elevation \_\_\_\_\_

Units Metric  U.S. Survey Foot

Horizontal Datum \_\_\_\_\_

Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_

Date of Survey APRIL 25, 2018

Vertical Datum \_\_\_\_\_

Complies with Public Resources Code §§ 8801-8819

Complies with Public Resources Code §§ 8890-8902

PLS Act Ref.:  8765(d)  8771  8773  Other:

Corner/Monument:  Left as found  Established  Rebuilt  Pre-Construction

Found and tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

PRE-CONSTRUCTION DOCUMENTATION OF THE FOUND 3/4" IRON PIPE ON THE EAST LINE OF CORRAL HOLLOW ROAD AND AT THE WESTERN CORNER OF PARCEL II OF INSTRUMENT NO. 82012429 PER 29 RS 138 WITHIN SECTION 17, T. 3 S. R 5 E. M.D.M.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on APRIL 25, 2018

Signed \_\_\_\_\_ P.L.S. No. 6441



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 25, 2018

and examined and filed JUNE 25, 2018

Signed James E Hart P.L.S. No. 8657

Title Acting COUNTY SURVEYOR



### County Surveyor's Comment

