COR	NER REC	ORD	Agency Index CR	- 18-168
			Document Number	0-1171
City of			maps & plats, Volume 2	n, California
——————————————————————————————————————	The state of the s			
CORNER TYPE			COORDINATES (Optional) NEE.	
11	Government Co	orner Control	Elevation	
×	Meander	Property	Units Metric	U.S. Survey Foot
	Rancho	X Other	Horizontal Datum	
	Date of Survey	August 6, 2018	Zone Epoch Vertical Datum	Date
T3N R61		, (agas, s, 20.0		sources Code §§8801-8819
MDBEM			Complies with Public Resources Code §§8890-8902	
PLS Act Ref.:	8765(d)	× 8771	8773	Other:
Corner/	Left as found	Established	Rebuilt	Pre-Construction
Monument:	Found and tagged	Reestablished	Referenced	Post-Construction
Cut "X" and Iron Pipe monuments were removed during new fence and driveway construction. Set iron pipe and magnail/washer to replace monuments as shown on sheet 2. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on August 6, 2018 Signed P.L.S. or R.C.E. No. 8166 COUNTY SURVEYOR'S STATEMENT				
This Corner Record was and examined and filed Signed Title Acting County Surveyor's County	October 23, 2 Hard County Sineyer	per 23, 2018 2018 P.L.S. #RCE. No.	8657	SIGNAL LAND SUBJECT OF CALIFORNIA OF CALIFORNIA

- FOUND ¾ IP WITH TAG ILLEGIBLE IN MONUMENT WELL
- FOUND 🖁 IP, NO TAG
- ➤ FOUND CUT CROSS 2.00' FROM FRONT LOT CORNER
- O SET 1"x30" IP TAGGED LS 8166
- SET BRASS WASHER & MAG NAIL LS 8166 AT 2' PROJECTION OF REAR LOT LINE



1"=40

REFERENCES:

(R) = AARON TERRACE, MAPS & PLATS, V25, P31, S.J.C.R.

