


# CORNER RECORD

Agency Index: CR-19-03

Document Number: \_\_\_\_\_

City of MANTECA County of SAN JOAQUIN, California

Brief Legal Description MONUMENTS ALONG THE CENTERLINE AND SOUTH RIGHT-OF-WAY OF SOUTHLAND ROAD LOCATED IN THE WEST HALF OF SECTION 28, T.1S, R.7E, M.D.B.&M



SEC. 28  
T.1S, R.7E

### CORNER TYPE

- Government Corner  Control   
 Meander  Property   
 Rancho  Other

Date of Survey 2-12-2018

### COORDINATES (Optional)

N. \_\_\_\_\_ E. \_\_\_\_\_

Elevation: \_\_\_\_\_

Units Metric  U.S. Survey Foot

Horizontal Datum: \_\_\_\_\_

Zone: \_\_\_\_\_ Epoch Date: \_\_\_\_\_

Vert. Datum: \_\_\_\_\_

- Complies with Public Resources Code SS8801-8819  
 Complies with Public Resources Code SS8890-8902

PLS Act Ref:  8765(d)  8771  8773  Other:

Corner/ Monument:  Left as found  Established  Rebuilt  Pre-Construction  
 Found and Tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

FOUND BOLT AND WASHER IN MONUMENT WELL AND TWO (2) 3/4" IRON PIPES TAGGED "LS 3730" PER 10-PM-55, AND FOUND 3/4" IRON PIPE TAGGED "LS 3730" PER 10-PM-125, S.J.C.R., LOCATED IN THE WEST HALF OF SECTION 28, T.1S, R.7E, M.D.B.&M.

SET THREE (3) 3/4" IRON PIPES TAGGED "LS 6953" AND CONCRETE NAIL TAGGED "LS 6953", AS WITNESS CORNERS, ALL AS SHOWN ON PAGE 2.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on OCTOBER 05, 2018,



Signed [Signature] P.L.S. or R.C.E. Number 6953

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received January 7, 2019

and examined and filed January 16, 2019

Signed James E. Hart P.L.S. or R.C.E. No: 8657

Title Acting County Surveyor

County Surveyor's Comment \_\_\_\_\_

