

# CORNER RECORD


Agency Index CR-19-07

Document Number \_\_\_\_\_

City of TRACY

County of SAN JOAQUIN, CALIFORNIA

Brief Legal Description NORTHWEST CORNER OF THE SURVEYED DESIGNATED REMAINDER AS FILED IN BOOK 23 OF PARCEL MAPS AT PAGE 49, OFFICIAL RECORDS OF SAN JOAQUIN COUNTY.



T2S R4E  
MDB+M

### CORNER TYPE

- Government Corner  Control
- Meander  Property
- Rancho  Other

Date of Survey NOVEMBER 13, 2018

### COORDINATES (Optional)

N. \_\_\_\_\_ E. \_\_\_\_\_

Elevation \_\_\_\_\_

Units Metric  U.S. Survey Foot

Horizontal Datum \_\_\_\_\_

Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_

Vertical Datum \_\_\_\_\_

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref:  8765 (d)  8771  8773  Other: \_\_\_\_\_

Corner/Monument:  Left as found  Established  Rebuilt  Pre-Construction  
 Found and tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:  
FOUND CONCRETE MONUMENT WITH 5 INCH BRASS DISK STAMPED "R.C.E. 7632" ABOUT 1 FOOT SOUTH OF THE POWER POLE ON THE SOUTHERLY RIGHT OF WAY LINE OF SCHULTE ROAD.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on NOVEMBER 26, 2018.

Signed [Signature] P.L.S. or R.C.E. No. 8654

Richard James Hickenbottom  
Kier & Wright Civil Engineers & Surveyors, Inc., Livermore, CA



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received January 8, 2019

and examined and filed January 17, 2019.

Signed [Signature] P.L.S. or R.C.E. No. 8657

Title Acting County Surveyor

County Surveyor's Comment \_\_\_\_\_



