CR-19-29 CORNER RECORD Agency Index: Document Number: SAN JOAQUIN County of ___ MANTECA Brief Legal Description MONUMENT LOCATED IN THE SOUTHEAST QUARTER OF SECTION 32, T.1S, R.7E, M.D.B.&M. CORNER TYPE COORDINATES (Optional) _ E. ___ Government Corner Control Elevation: Meander Property X Metric U.S. Survey Foot Units Rancho Other Horizontal Datum: Zone: _____ Epoch Date: __ 01-28-2019 Vert. Datum: Date of Survey SEC. 32 Complies with Public Resources Code SS8801-8819 T.1S, R.7E Complies with Public Resources Code SS8890-8902 PLS Act Ref: 8765(d) X 8771 8773 Other: Corner/ XLeft as found Established Rebuilt Monument: Found and Tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: \boxtimes See sheet #2 for description(s): FOUND A CUT "X" 2.5' BEHIND THE BACK OF SIDEWALK NEAR THE NORTHEAST CORNER OF LOT 28 AS SHOWN ON THAT MAP OF THE TOWN OF NORTH MANTECA FILED FOR RECORD IN BOOK 5 OF MAPS & PLATS AT PAGE 11, S.J.C.R., LOCATED IN THE SOUTHEAST QUARTER OF SECTION 32, T.1S, R.7E, M.D.B.&M. SET THREE (3) CONCRETE NAILS WITH BRASS TAGS "LS 6953" AS WITNESS CORNERS, AS SHOWN ON PAGE 2. SURVEYOR'S STATEMENT LAND This Corner Record was prepared by me or under my direction in conformance with KENT A. FEBRUARY 01 HYSELL the Land Surveyors' Act on ND, 6953 ____P.L.S. or R.C.E. Number ___ Signed COUNTY SURVEYOR'S STATEMENT This Corner Record was received March 11, 2019 and examined and filed March 26, 2019

BPELSG-2016

County Surveyor's Comment

