

# CORNER RECORD


Agency Index CR-19-55

Document Number \_\_\_\_\_

City of Lodi

County of San Joaquin, California

Brief Legal Description SE corner Parcel A, 6-PM-151

<b>CORNER TYPE</b>		<b>COORDINATES (Optional)</b>
	Government Corner <input type="checkbox"/> Control <input type="checkbox"/>	N. _____ E. _____
	Meander <input type="checkbox"/> Property <input checked="" type="checkbox"/>	Elevation _____
	Rancho <input type="checkbox"/> Other <input type="checkbox"/>	Units Metric <input type="checkbox"/> U.S. Survey Foot <input type="checkbox"/>
	Date of Survey <u>2017-12-11</u>	Horizontal Datum _____
		Zone _____ Epoch Date _____
		Vertical Datum: _____
		<input type="checkbox"/> Complies with Public Resources Code §§8801-8819
		<input type="checkbox"/> Complies with Public Resources Code §§8890-8902

PLS Act Ref.:  8765(d)  8771  8773 Other: \_\_\_\_\_

Corner/Monument:  Left as found  Established  Rebuilt  Pre-Construction  
 Found and tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:  
 See sheet #2 for description(s):

FOUND 3/4" IRON PIPE, BADLY DETERIORATED, AT THE BACK OF SIDEWALK FOR THE SOUTHEAST CORNER OF PARCEL "A" AS SHOWN ON THE PARCEL MAP FILED IN BOOK 6 OF PARCEL MAPS, AT PAGE 151, SAN JOAQUIN COUNTY RECORDS. SET SWING TIES AS SHOWN PRIOR TO CONSTRUCTION NEAR THIS LOCATION.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyor's Act on MAY 10<sup>TH</sup>, 2019.  
 Signed [Signature] P.L.S. or R.C.E. No.: 8366




### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received May 21, 2019 and examined and filed June 4, 2019.  
 Signed James E. Hart P.L.S. or R.C.E. No.: 8657  
 Title County Surveyor



County Surveyor's Comment \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_



### WEST KETTLEMAN LANE

