CORNER RECORD Agency Index Document Number Manteca County of California City of San Joaquin Brief Legal Description Southwest intersection of Main Street and Lupton Street. **CORNER TYPE COORDINATES (Optional) Government Corner** Control Elevation U.S. Survey Foot X Metric Property Meander Units Rancho Other Horizontal Datum _____ **Epoch Date** Date of Survey August 2, 2019 Vertical Datum Complies with Public Resources Code §§8801-8819 Sec. 5, T.2S., R.7E., M.D.B. & M. Complies with Public Resources Code §§8890-8902 PLS Act Ref.: X 8771 8765(d) 8773 Other: Left as found Established Pre-Construction Rebuilt Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: ✓ See sheet #2 for description(s): SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with **COUNTY SURVEYOR'S STATEMENT** September 10, 2019

September 18, 2019

P.L.S. OFRIG.E. No. 8657 This Corner Record was received



and examined and filed

County Surveyor's Comment

Signed

Title

Job No.: 2019-183 - B

R.S. 19-194

LUPTON STREET

9.62'(M)

FD. 1" IRON PIPE PER (A),-BENT, REPLACED WITH 3/4" X 12" IRON PIN W/TAG STAMPED LS 4450

REFERENCE

(A) R.S. 19-194, S.J.C.R.



SCALE: 1" = 4'2019-183 -B

LEGEND

INDICATES FOUND MONUMENT AS NOTED

INDICATES SET MAG. NAIL AND ALUMINUM WASHER STAMPED LS 4450

INDICATES FOUND ON THIS SURVEY

R.S. INDICATES RECORD OF SURVEY, BOOK AND PAGE, S.J.C.R.

S.J.C.R. INDICATES SAN JOAQUIN COUNTY RECORDS INDICATES MEASURED ON THIS SURVEY (M)