CORNER RECORD

Document Number City of MANTECA County of SAN JOAQUIN Brief Legal Description A portion of the south 1/2 of the southwest 1/4 of Section 5, T.2S., R.7E. **CORNER TYPE** COORDINATES (Optional) Government Corner X Control Elevation Meander X U.S. Survey Foot Property Units Metric Rancho Other Horizontal Datum Zone _ Epoch Date Date of Survey January 30, 2020 Vertical Datum Complies with Public Resources Code §§8801-8819 SEC. 5 Complies with Public Resources Code §§8890-8902 T.2S., R. 7E. PLS Act Ref.: 8765(d) X 8771 8773 Other: Left as found Established Rebuilt Pre-Construction Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): Referencing a 2" Brass Disk, stamped "CALIF. DEPT. OF TRANSPORTATION RM 236". Three reference marks, all being nail & brass washer stamped "RP LS 9313" were set to preserve monument locations prior to construction. Found monument is on the existing shoulder of the eastbound lane of State Route 120 approximately 1960 feet east of Union Road. See sheet 2 for details. SURVEYOR'S STATEMENT SAMUEL R. This Corner Record was prepared by me or under my direction in conformance with **MCINTYRE** the Professional Land Surveyors' Act on Signed P.L.S. or R.C.E. No. **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received and examined and filed Signed Title **County Surveyor's Comment**


CR-20-112

Agency Index

REFERENCE:

(1) BOOK 28 OF RECORD OF SURVEYS AT PAGE 129, SAN JOAQUIN COUNTY RECORDS

STATE ROUTE 120



⊙ SET NAIL & WASHER STAMPED "RP LS 9313"

THE PURPOSE OF THIS RECORD IS TO DOCUMENT THE PERPETUATION OF FOUND MONUMENT(S) PURSUANT TO THE PLS ACT SECTION 8771.