CR-21-017 Agency Index: CORNER RECORD Document Number: SAN JOAQUIN , California County of _____ City of LATHROP Brief Legal Description MONUMENTS AT THE INTERSECTIONS OF LOUISE AVENUE AND FIFTH STREET AND THE SOUTH QUARTER CORNER OF SECTION 26 ALONG CENTERLINE OF LOUISE AVENUE. CORNER TYPE COORDINATES (Optional) ____ E. ____ Government Corner Control Elevation Property Meander U.S. Survey Foot Metric Units --- 26 --- ○ Other Rancho Horizontal Datum Zone _____ Epoch Date _____ Date of Survey 10-20-2020 Vertical Datum T.1S, R.6E Complies with Public Resources Code SS8801-8819 Complies with Public Resources Code SS8890-8902 8765(d) 8771 8773 Other: PLS Act Ref: Left as found Established Rebuilt □ Pre−Construction Corner/ X Referenced ☐ Post—Construction Found and Tagged Reestablished Monument: Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND ONE (1) 3/4" IRON PIPE, TAGGED "L.S. 5122", IN A MONUMENT WELL ALONG THE CENTERLINE OF LOUISE AVENUE AT THE SOUTH QUARTER CORNER OF SECTION 26 AS SHOWN ON THE RECORD OF SURVEY FILED FOR RECORD IN BOOK 36 OF SURVEYS AT PAGE 147, S.J.C.R.; AND ONE (1) 5" BRASS DISK, STAMPED "D&L FDRY", IN A MONUMENT WELL AT THE INTERSECTION OF LOUISE AVENUE AND FIFTH STREET AS SHOWN ON THE PARCEL MAP FILED FOR RECORD IN BOOK 26 OF PARCEL MAPS AT PAGE 94, S.J.C.R. SET SIX (6) CONCRETE NAILS WITH BRASS TAGS, MARKED "L.S. 6953", AS WITNESS CORNERS. ALL AS SHOWN ON PAGE 2. SURVEYOR'S STATEMENT EN LAND This Corner Record was prepared by me or under my direction in conformance with KENT A. HYSELL the Land Surveyors' Act on _____JANUARY 7 , 2021 , ND, 6953 P.L.S. or R.C.E. Number 6953 OF CAL COUNTY SURVEYOR'S STATEMENT This Corner Record was received January 11, 2021 and examined and filed January 19, 2021 P.L.S. or R.C.E. No: 8657 Sianed _ Title County Surveyor's Comment _.____

