## CORNER RECORD

Agency Index Document Number San Joaquin County of Stockton Found monument as noted, referenced and left as found. Brief Legal Description **COORDINATES (Optional) CORNER TYPE** Elevation Government Corner Control U.S. Survey Foot X Property Metric Units Meander Other Rancho Horizontal Datum Zone Epoch Date Date of Survey September 12, 2020 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: X 8771 8773 8765(d) PLS Act Ref.: Pre-Construction Left as found Established Rebuilt Corner/ Monument: Referenced Post-Construction Found and tagged Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: ✓ See sheet #2 for description(s): Found a cut cross in the concrete sidewalk near the northwest curb return of Miner Ave and Hunter St. Set four (4) reference points, as noted on the reverse, outside of the construction limits. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on January 31, 2022 LANDRUM P.L.S. or R.C.E. No. 5837 Signed **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received and examined and filed Signed Title **County Surveyor's Comment** 

