

CORNER RECORD

Agency Index CR-22-115


Document Number _____

City of _____ County of San Joaquin, California

Brief Legal Description Portion of northeast quarter of Section 10, T.2 S., R.8 E., M.D.M.

CORNER TYPE

COORDINATES (Optional)



S.10 T.2S.,R8E
M.D.M.

Government Corner Control

Meander Property

Rancho Other

Date of Survey May 10, 2019

N. _____ E. _____

Elevation. _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref.: 8765(d) 8771 8773 Other:

Corner/Monument: Left as found Established Rebuilt Pre-Construction

Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

Found monuments as shown on 17 PM 44, that may be affected by trench construction.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyor's Act on May 10, 2019

Signed [Signature] P.L.S. or R.C.E. No. PLS 5443



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received March 16, 2022

and examined and filed April 4, 2022

Signed James E. Hart P.L.S. or R.C.E. No. 8657

Title County Surveyor

County Surveyor's Comment _____



D.D. SHEET No. 61

