CORI	VER F	RECO	RD		CR ZZ-118
City of Stockto	an .		Country of	San Jagguin	, California
Brief Legal Description <u>Lot 11, Block 80 South of Mormon Channel, City of Stockton</u>					
CORNER TYPE				COORDINATES (Optional)	
+	Governmen	nt Corner	Control \square	N Elevation.	E
	Meander Property				U.S. Survey Foot 🛛
	Rancho Dther				
1				Horizontal DatumEpoch Date	
□ L Date of Survey January 14, 2022 Vertical Datum □ Complies with Public Resources Code §§8801-8819 □ Complies with Public Resources Code §§8890-8902					
			_	Compiles with Public	Resources Gode §§8890-8902
PLS Act Ref.:	8765(d)	<u>X</u>	8771	8773	Other:
Corner/ Monument:	Left as found	_	Established	Rebuilt	☐ Pre-Construction
	☐ Found and ta	agged X	Reestablished	Referenced	☐ Post-Construction
See sheet #2 for description(s): Found old 3/4" iron pipes for the northeast and southeast corners and found a very old 2"x2" redwood stake at the southwest corner of Lot 11 Block 80, south of Mormon Channel. Found other monuments and chiseled crosses per references as shown, to confirm Block 80. Measured Block 80 substantially conforms with Stockton standard measurements and measurements shown on reference (F) on the back of this cover page. Set corners of Lot 11 as shown. This Corner Record is being filed in conjunction with City of Stockton building permit BP21-00615 SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyor's Act on January 17, 2022 P.L.S. or R.C.E. No. PLS 5443					
COUNTY SURVEYOR'S STATEMENT					
This Corner Record was and examined and filed Signed Title County Surveyor's	April Enfant Surreyor	March 10 7, 2022 — P.L	6, 2022 2 s. o r R.C.E . No.	8657	LICENSE No. 8657 CALIFORNIA CON AL LAND SUPPLY OF CALIFORNIA A PART OF CALIFORNIA A

D.D. SHEET No.31C

BEPELSG-2016

