CR-23-192 Agency Index CORNER RECORD **Document Number** City of STOCKTON County of SAN JOAQUIN Brief Legal Description LINE COMMON TO LOTS 221 AND 222 OF "QUAIL LAKES, UNIT NO. 4" BOOK 21 OF MAPS AND PLATS, PAGE 28, S.J.C.R. **CORNER TYPE** COORDINATES (Optional) E. Elevation Government Corner Control U.S. Survey Foot Units Metric □ Property Meander Other Horizontal Datum Rancho Zone Epoch Date Vertical Datum Date of Survey 4/21/2023 T.2N., R.6E. Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref: 28765(d) 8773 Other: **⊠** 8771 Established Rebuilt ☐ Pre-Construction Corner/ Left as found Monument: □ Post-Construction ☐ Found and tagged ☐ Reestablished Referenced Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description (s): FOUND FOUR (4) CONCRETE NAILS WITH BRASS TAG "LS 6953" AS WITNESS CORNERS (R1); SET ONE (1) CONCRETE NAIL WITH BRASS TAG "LS 6953", ALL AS SHOWN ON SHEET 2. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on JUNE 22, 2023 _____ P.L.S. or R.C.E. No.__ Signed_ COUNTY SURVEYOR'S STATEMENT This Corner Record was received_ and examined and filed, ____ P.L.S. or R.C.E. No. **865**7 County Surveyor's Comment ___

