

CORNER RECORD


Agency Index CR-24-063
Document Number _____

City of STOCKTON County of SAN JOAQUIN, California

Brief Legal Description WITHIN E ROSE ST AND N CALIFORNIA ST INTERSECTION

CORNER TYPE

COORDINATES (Optional)



- Government Corner
- Meander
- Rancho
- Control
- Property
- Other

Date of Survey 10/21/2023

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref.: 8765(d) 8771 8773 Other:

Corner/Monument: Left as found Established Rebuilt Pre-Construction

Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

FOUND CUT "X" ON TOP CONCRETE CURB WITHIN THE INTERSECTION OF EAST ROSE STREET AND NORTH CALIFORNIA STREET. SET FOUR CUT "X" AS STRADDLERS FOR FOUND MONUMENT SHOWN ON SHEET 2. NO PREVIOUS 8771b CORNER RECORD ON FILE. CONTRACT MON #1050.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on JANUARY 12, 2024

Signed Carl L. Betz P.L.S. or R.C.E. No. LS 5650



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received January 22, 2024

and examined and filed February 8, 2024

Signed James E. Hart P.L.S. or R.C.E. No. 8657

Title County Surveyor

County Surveyor's Comment



LEGEND

- ☒ FOUND CUT "X" ON TOP OF CONCRETE CURB
- ☒ SET CUT "X" ON TOP OF CURB UNLESS OTHERWISE SPECIFIED
- GATE POST

--- LOT LINE

-x-x-x-x-x- WOOD FENCE
(M) MEASURED ON THIS SURVEY

