CR-24-092 **CORNER RECORD** Agency Index **Document Number** SAN JOAQUIN California City of STOCKTON County of Brief Legal Description WITHIN E 5TH ST AND S CALIFORNIA ST INTERSECTION COORDINATES (Optional) CORNER TYPE E. N. Elevation Government Corner Control U.S. Survey Foot Units Metric Meander Property Rancho Other Horizontal Datum Zone **Epoch Date** Date of Survey 12/02/2023 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8771 8773 PLS Act Ref .: 8765(d) Pre-Construction Established Rebuilt Left as found Corner/ Monument: Post-Construction X Referenced Found and tagged Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND CUT "X" ON CONCRETE HANDICAP RAMP WITHIN THE INTERSECTION OF EAST 5TH STREET AND SOUTH CALIFORNIA STREET. SET FOUR CUT "X" AS STRADDLERS FOR FOUND MONUMENT SHOWN ON SHEET 2. NO PREVIOUS 8771b CORNER RECORD ON FILE. CONTRACT MON #1004. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with JANUARY 12, 2024 PLS 5650 the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. Signed CAL COUNTY SURVEYOR'S STATEMENT ived <u>January</u> 22, 2024 February 8, 2024 E Hant P.L.S. OFR.C.E. No. 8657 This Corner Record was received and examined and filed LICENSE Signed NO. 8657

County Surveyor's Comment

Title

