

CORNER RECORD

Agency Index CR-24-096


Document Number _____

City of STOCKTON County of SAN JOAQUIN, California

Brief Legal Description WITHIN E 6TH ST AND S CALIFORNIA ST INTERSECTION

CORNER TYPE

COORDINATES (Optional)



- Government Corner
- Meander
- Rancho
- Control
- Property
- Other

Date of Survey 12/02/2023

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref.: 8765(d) 8771 8773 Other:

Corner/Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

FOUND MAG NAIL IN AC PAVEMENT WITHIN THE INTERSECTION OF EAST 6TH STREET AND SOUTH CALIFORNIA STREET. SET FOUR CUT "X" AS STRADDLERS FOR FOUND MONUMENT SHOWN ON SHEET 2. NO PREVIOUS 8771b CORNER RECORD ON FILE. CONTRACT MON #1016.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on JANUARY 12, 2024

Signed Carl L. Betz P.L.S. or R.C.E. No. LS 5650



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received January 22, 2024 and examined and filed February 8, 2024

Signed James E. Hart P.L.S. or R.C.E. No. 8657
Title County Surveyor

County Surveyor's Comment _____



LEGEND

- FOUND MAG NAIL IN AC PAVEMENT
- ⊠ SET CUT "X" ON CONCRETE SIDEWALK UNLESS OTHERWISE SPECIFIED
- TW TREE WELL
- MH MANHOLE
- ⊙ GATE POST

--- LOT LINE
 ○---○ CHAIN LINK FENCE
 (M) MEASURED ON THIS SURVEY

