## CORNER RECORD

CR-25-270 Agency Index Document Number County of SAN JOAQUIN Brief Legal Description PRE-CONSTRUCTION TIES FOR MONUMENT PRESERVATION **CORNER TYPE COORDINATES (Optional)** \_\_\_E. \_\_\_ Government Corner X Control Elevation V.S. Survey Foot Meander Units Property Rancho Horizontal Datum Epoch Date Zone Date of Survey July 14, 2025 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: 8765(d) 8771 X Other: Left as found Established Rebuilt X Pre-Construction Corner Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): PRE-CONSTRUCTION TIES FOR MONUMENT PRESERVATION ON FARMINGTON ROAD, STATE ROUTE 4, NEAR INTERSECTION WITH WALKER LANE SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on July 16, 2025 Signed COUNTY SURVEYOR'S STATEMENT August 21, 2025 This Corner Record was received and examined and filed Signed No. 8657 Title **County Surveyor's Comment** 

TIE ELEVATION 34.57'

TIE ELEVATION 34.12'

TIE ELEVATION 34.14'
TIE ELEVATION 34.46'

D.

E. F.