


CORNER RECORD

Agency Index

CR-26-251

Document Number

City of Tracy County of San Joaquin, CaliforniaBrief Legal Description Monument 30' South of South Quarter Corner of Section 26, T2S, R4E MDB&M**CORNER TYPE****COORDINATES (Optional)**

- | | |
|--|---|
| ☐ Government Corner | ☐ Control |
| ☐ Meander | ☐ Property |
| ☐ Rancho | ☒ Other |

Date of Survey June 10, 2026

N. _____ E. _____

Elevation _____

Units ☐ Metric ☒ U.S. Survey FootHorizontal Datum NAD83Zone 3 Epoch Date _____

Vertical Datum _____

☐ Complies with Public Resources Code §§8801-8819☐ Complies with Public Resources Code §§8890-8902

SEC.35, T2S, R4E MDB&M

PLS Act Ref.: ☐ 8765(d) ☒ 8771 ☐ 8773 ☐ Other:

Corner/ Monument:	☒ Left as found	☐ Established	☐ Rebuilt	☒ Pre-Construction
	☐ Found and tagged	☐ Reestablished	☐ Referenced	☐ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☐ See sheet #2 for description(s):

Monument at Southerly Right of Way of Schulte Road, 30' south of the monument at the South Quarter Corner of Section 26, as shown on the Record of Survey filed for record on July 17, 2017, in Book 39 of Surveys at Page 23, San Joaquin County Records.

Said monument is in danger of being disturbed by construction and is described as follows:
2 inch brass disk in monument well, not stamped

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on July 22, 2026Signed Garry K. Lamb (P.L.S. or R.C.E. No. PLS 6627)**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received

and examined and filed

Signed Robert L. Borsdorf III P.L.S. or R.C.E. No. 9728Title County Surveyor

County Surveyor's Comment





0 500' 1000' 2000'
Scale 1" = 1000'

