


CORNER RECORD

COUNTY OF San Joaquin T. 3 N R. 7 E MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☐
 CORNER IDENTIFICATION - DATE OF VISIT Dec. 19 19 74



corner 12

CORNER - LEFT AS FOUND ☒ FOUND AND TAGGED ☐ REESTABLISHED OR LITERATED CORNER ☐ RESULT ☐


PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

1 1/4" O.D. Iron Pipe Flush with natural ground. Located in line with the projection of westerly wire fence. 11°+ S/O burned out oak snag (50" live oak) in line with projection of road southerly.


PHYSICAL DESCRIPTION OF MONUMENTS RESULT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐
 STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



PACIFIC GAS AND ELECTRIC CO.
 LAND DEPT. JOB 103720



COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED MARCH 19, 19 75
 AND EXAMINED AND FILED MARCH 21, 19 75
 BY: Robert D. Schumaker
 TITLE: Chief Deputy County Surveyor
 DOCUMENT NO. CR-75-006
 STATEMENT ON BACK OF SHEET

YES ☐ NO ☒